ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura

Street ID	Street Name	Significant Landmark
W0432, W0659, W0657, W0661	NA	Canara bank layout cross roads

Segment No.	Total Length (m)
9/S-W0432/S114036	287.49

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	26.40	77.579494	13.069460	77.579640	13.069269	W0659	W0436
2	42.62	77.579321	13.070278	77.579207	13.069909	W0432	W0661
3	74.83	77.579681	13.070211	77.579485	13.069563	W0432	W0661
4	143.64	77.579749	13.070247	77.581008	13.069842	W0667	W0659

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to roads at Canara bank layout cross roads in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	1000000	2015

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements and Asphalting to roads at Canara bank layout cross roads in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone	009-14-000053

Work Order No.	Work Order Date	Period of Extention
EE/BTP/ BBMP/E-PMT/WO/370/2015-16	24/03/2015	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
30/01/2016	29/01/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

B B UMESHA	0.00

Phone No. **E-Mail ID**

9886213563

Field Inspection Details

Number of Trees	Any Other Information	Name
12		SURESH
Date of Inspection	**Remarks**	
25/03/2017	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/03/2017	24/04/2017	COMPLETED
SE	VASU K M	25/03/2017	24/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0432, W0659, W0657, W0661

EE	YARAPPA REDDY	25/03/2017	24/04/2017	COMPLETED
AEE	SHIVAKUMAR	25/03/2017	24/04/2017	COMPLETED
AE	SURESH	25/03/2017	24/04/2017	COMPLETED
AE	SURESH	25/03/2017	24/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0432, W0659, W0657, W0661